

Canon 5D Mark III_ Internal Temperature to High

Problem:

Internal temperature to high, anybody seen this? Shutter or Main PCB?

Solution:

We found that Canon starting with EOS 40D and the 5D M III, has the internal heat sensor on a most unusual place. on the prism unit on the in-finder LED fpc after replacing the prism problem solved. The reason we ordered a prism unit, the in-finder LED is not available separately.



